

TIPS Corp Code

57116

Location	Quantity	Price	Service Description
USD 202 High Scholl	1	\$2,201.57	Sprinkler/ Backflow Inspection
USD 202 High Scholl	1	\$4,225.68	Alarm
USD 202 High Scholl	1	\$1,091.43	Kitchen
USD 202 High Scholl	1	\$754.03	Fire extinguisher
Total		\$8,272.71	
USD 202 Oak Grove	1	\$740.99	Sprinkler / Backflow Inspection
USD 202 Oak Grove	1	\$1,492.68	Alarm
USD 202 Oak Grove	1	\$301.70	Kitchen
USD 202 Oak Grove	1	\$138.77	Fire extinguisher
Total		\$2,674.14	
USD 202 Turner Elem	1		Sprinkler Inspection
USD 202 Turner Elem	1	\$1,437.68	Alarm Inspection
USD 202 Turner Elem	1	\$223.46	Kitchen
USD 202 Turner Elem	1	\$517.12	Fire extinguisher
Total		\$2,178.26	
USD 202 Junction Elem	1		Sprinkler / Backflow Inspection
USD 202 Junction Elem	1	\$1,185.68	Alarm
USD 202 Junction Elem	1	\$223.46	Kitchen
USD 202 Junction Elem	1	\$481.97	Fire extinguisher
Total		\$1,891.11	
USD 202 Journey School	1	\$0.00	Sprinkler Inspection
USD 202 Journey School	1	\$961.68	Alarm Inspection
USD 202 Journey School	1	\$383.05	Kitchen
USD 202 Journey School	1	\$203.26	Fire extinguisher
Total		\$1,547.99	
USD 202 Midland Trail	1	\$0.00	Sprinkler Inspection
USD 202 Midland Trail	1	\$2,718.68	Alarm Inspection
USD 202 Midland Trail	1	\$291.10	Kitchen
USD 202 Midland Trail	1	\$370.37	Fire extinguisher
Total		\$3,380.15	
6th Grade Academy	1	\$0.00	Sprinkler Inspection
6th Grade Academy	1	\$984.68	Alarm Inspection
6th Grade Academy	1	\$223.46	Kitchen
6th Grade Academy	1	\$266.40	Fire extinguisher
Total		\$1,474.54	
USD 202 Administrative	1	\$0.00	Sprinkler Inspection
USD 202 Administrative	1	\$0.00	Backflow Inspection
USD 202 Administrative	1	\$0.00	Kitchen
USD 202 Administrative	1	\$172.21	Fire extinguisher
Total		\$172.21	
USD 202 Recreation	1	\$0.00	Sprinkler Inspection
USD 202 Recreation	1	\$0.00	Backflow Inspection
USD 202 Recreation	1	\$301.70	Kitchen
USD 202 Recreation	1	\$104.12	Fire extinguisher
Total		\$405.82	
USD 202 Bus Barn	1	\$0.00	Sprinkler Inspection
USD 202 Bus Barn	1	\$597.68	Alarm Inspection
USD 202 Bus Barn	1	\$0.00	Kitchen
USD 202 Bus Barn	1	\$962.67	Fire extinguisher

Total		\$1,560.35
USD 202 Dist Activity Center	1	\$405.65 Backflow Inspection
USD 202 Dist Activity Center	1	\$835.36 Alarm Inspection
USD 202 Dist Activity Center	1	\$0.00 Kitchen
USD 202 Dist Activity Center	1	\$97.19 Fire extinguisher
Total		\$1,338.20
USD 202 Turner MX Building	1	\$0.00 Sprinkler Inspection
USD 202 Turner MX Building	1	\$0.00 Backflow Inspection
USD 202 Turner MX Building	1	\$0.00 Kitchen
USD 202 Turner MX Building	1	\$303.64 Fire extinguisher
Total		\$303.64
USD 202 Middle School	1	\$1,435.66 Sprinkler / Backflow Inspection
USD 202 Middle School	1	\$7,040.36 Alarm
USD 202 Middle School	1	\$1,678.95 Kitchen
USD 202 Middle School	1	\$282.11 Fire extinguisher
Total		\$10,437.08

Total	\$35,636.20
--------------	--------------------